

Changelog: Taster Light 55

BE-TAL5501.x1, BE-TAL55T1.x1, BE-TAL5502.x1, BE-TAL55T2.x1



English version on bottom pages

Datum: 09.08.2019



Datenbank-version (ETS)	Datum	Datenbank Änderungen	Datenbank-Dateiname
v1.0	02.07.2019	initial	

Hardware-version	Datum	Hardware Änderungen	Kompatibilität zu Datenbanken
R1.2	09.08.2019	- Bugfix: LED-Verhalten mit internem Objekt - Bugfix: LED-Verhalten mit externem Objekt 1Byte DPT 5.001 Prozent	alle
R1.1	27.06.2019	Initial	alle

Hinweis: die Hardwareversion steht auf der rechten Gehäuseseite

Hinweis: die Datenbankversion ist in der ETS unter Programmversion zu finden

Changelog: Push Button Lite 55

BE-TAL5501.x1, BE-TAL55T1.x1, BE-TAL5502.x1, BE-TAL55T2.x1



English version on bottom pages

Date: 09.08.2019



Database-version (ETS)	Date	Database changes	Database-Filename
v1.0	02.07.2019	initial	

Hardware-version	Date	Hardware changes	Compatibility to databases
R1.2	09.08.2019	- Bugfix: LED-behaviour with internal object - Bugfix: LED-behaviour with external object 1Byte DPT 5.001 Percent	all
R1.1	27.06.2019	Initial	all

Note: The Hardwareversion can be found on the housing.

Note: The database-version (Program Version) can be found in ETS.